

Detroit Dam Electrical Failure and Fire

*Some Protective System
Lessons Learned – NW
Hydro Operators Regional
Forum May 22, 2008*




**US Army Corps
of Engineers.**


Portland District




Detroit Dam









JULY 22, 1947		Engineering Department	RECEIVED BY
RECEIVED BY	DATE	DESCRIPTION	APPROVED
CORPS OF ENGINEERS, U.S. ARMY NORTH PACIFIC DIVISION, PORTLAND, OREGON			
SHIPPED BY	DETROIT DAM	WILLAMETTE BASIN PROJECT, OREGON	
MAILED BY	NORTH SANTIAM RIVER	POWERHOUSE - ARRANGEMENT	
DISPATCHED BY	TRANS. SECT. THRU UNIT NO. 2		
PREPARED BY	<i>C. L. Tappan</i>		
SUPERVISOR	<i>C. L. Tappan</i>	APPROVED	<i>Overholt</i>
ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED		DATE 2-20-08 BY SP&C NO.	
DISTRIBUTION STATEMENT A:		REF ID: A64925	
DEPT 2-0-0/8			

Detroit Fire: Context

- Project was undergoing a phased but piece-meal multi-year modernization program:
 - Bridge crane
 - Main Unit Breaker replacement completed in 2004
 - Rewinding Detroit generators
 - Unit 1 was almost complete – but was still out of service
 - SCADA control upgrades
 - 13.8 kV station service breaker replacement project just completed
 - Station service distribution transformer and 480 volt switchgear replacement planned but not yet started

Detroit Fire Immediate Cause Under-rated Surge Arresters 2004

- A contract modification added arresters to temporarily protect several old transformers that would not be replaced until the next phase.
- 12.7kV MCOV proposed and approved.
- 10.2kV MCOV installed (10 sec @13.8kV).



Detroit Fire Causal Analysis

18 June Event Sequence

- Ground fault comes in hard.
- Big Cliff unit trips as designed.
- XJ2, XJ3, XJ5 trip as designed.
- Lights go out.
- Operator gets help.
- Lighting restored.



Detroit Fire Causal Analysis

Start of Fire

- Operator re-closed the circuit breaker energizing the firmly faulted bus.
- 13.8kV ground fault still there.
- Surge Arresters see high voltage.
- Surge Arresters burn.
- Reactor limits fault current
- No relay action since operator did not restart the tripped generator



Detroit Fire Causal Analysis

Relay Power Tagged Out, May 07


- Fire burns into XJ5 activating other protective devices – but:
 - A clearance had been taken for the purpose of performing some work on T1 before U1 was returned to service
 - This unknowingly disabled the secondary protective system trip
 - No line lock out relay function.



Detroit Fire Causal Analysis

Original Design – 1950's

- Unrealized plans for second yard breaker.
- Yard breaker only tripped by T1 pilot wires or 86L1
- T2 pilot wires do nothing.
- 86L2 must trip 86L1 to trip yard Breaker
- Compromise at the time based on best practices, costs, assumptions.



Detroit Fire Causal Analysis

Fire Propagation


- XJ5 Burns
- Still No Relay Action



Detroit Fire Causal Analysis

Fire Propagation

- XJ9 Burns
- Still No Relay Action



Detroit Fire Causal Analysis

Energy Source Removed

- Bus burns to current limiting reactor.
- Current increases
- BPA over-current relay trips.



Failure Events: Summary

- BPA ground fault
- New under-rated surge arresters burn
- 2 circuit breakers burn
- BCL bus melted
- Fault bypasses reactor
- Substation breaker clears the fault
- Soot and smoke everywhere




Damage Assessment

- XJ5, XJ9 circuit breakers
- Surge arresters & capacitors
- Metering PTs, CTs
- Switchgear enclosures
- Portions of the isolated phase bus work
- Soot everywhere (environmental clean up \$2+M)
- Current estimate - \$6.5m






















Electrical System Lessons Learned

- The critical need to keep electrical drawings up to date
- The critical need to carefully evaluate every modification phase in the full context of the protection system operation
- The value of periodically revisiting electrical protection schemes for each project
- The need to revisit clearance procedures to insure they actually do not do more than expected

Other Lessons Learned

- The need to provide more comprehensive operating staff training, especially during time of modernization
- The higher risk of multi-year phased piece-meal modifications to operating electrical distribution systems.
- The lower risk of a holistic system replacement strategy

Things We Are Doing Different

- Redesigning the protective relay systems to automatically isolate problems
 - Reducing the steps an operator needs to take to safely troubleshoot a station service power problem
 - Decreasing the amount of special knowledge needed to operate safely
- Adding new levels of protection that were not cost effective in the past
 - New multipurpose digital devices allow levels of protection not affordable in the past

Things We Are Doing Different

- Carefully coordinating our protective relay settings with BPA
- Implementing a system wide program to revisit protective systems at each project
- Implementing a comprehensive program to update critical project drawings

Things We Are Doing Different

- Improving station service control panel switch labeling
- Improving the event recording part of our SCADA

Questions?

